Moore's 1834 Detector for US \$2.50 and \$5 Showing a Top View of its Balance Beam Elements. 2) Moore's 1834 Detector Showing a Side View of its Balance Beam Elements. 3) George Howard 1849 Detector Showing its \$1 and \$2.50 Coin Holders on its One Swinging Arm which Partly Covers the Balance Beam and its Other Coin Holders. 4) George Howard 1849 Detector Showing its One Swinging Arm Turned onto the Counterweight Side of the Fulcrum. The Overlapping \$10 and \$20 Coin Holders on the Balance Beam Cause Diagonal Slot Guages to be Used. 5) George Howard 1849 Detector Showing a Side View of its Balance Beam and its One Partly Raised Swinging Arm. 6) Allender 1850 Detector with its Balance Beam Coin Holders on Each side of the Fulcrum. Its Separate Circular Weight is to be Placed in the \$1 Coin Holder for Testing the \$10 and \$20 Coins. Meyers 1850 Detector Showing its Two Swinging Arms with their Coin Holders Partly Covering the Balance Beam Coin Holders.

final

- 8) Meyers 1850 Detector Showing \$1 and \$2.50 Coin Holders on its top Swinging Arm Turned onto the Counterweight Side of the Fulcrum, Exposing the Other Swinging Arm with the \$5 Coin Holder and Further Exposing the \$10 and \$20 Coin Holders on the Balance Beam.
- 9) Meyers 1850 Detector Showing Both Swinging Arms turned onto the Counterweight Side of Fulcrum, Fully Exposing the \$10 and \$20 Coin Holders on the Balance Beam.
- 10) Meyers 1850 Detector Showing a Side View of the Balance Beam with its Two Swinging Arms in Partly Raised Positions.

for US \$2,50 and \$5

- 1) Moore's 1834 Detector Showing a Top View of its Balance Beam Elements.
- Moore's 1834 Detector Showing a Side View of its Balance Beam Elements.
 - George Howard 1849 Detector Showing its \$1 and \$2.50 Coin Holders on its One Swinging Arm which Partly Covers the Balance Beain and its Holders.

_ other Coin

- 4) George Howard 1849 Detector Showing its One Swinging Arm Turned onto the Counterweight Side of the Fulcrum. The Overlapping \$10 and \$20 Coin Holders on the Balance Beam Cause Diagonal Slot Guages to be Used.
- 5) George Howard 1849 Detector Showing a Side View of its Balance Beam and its One Partly Raised Swinging Arm
- 6) Allender 1850 Detector with its Balance Beam Coin Holders on Each side of the Pulcrum. Its Separate Circular Weight is to be Placed in the \$1 Coin Holder for Testing the \$10 and \$20 Coins.
- Meyers 1850 Detector Showing its Two Swinging Arms with their Coin Holders Partly Covering the Balance Beam Coin Holders.

Marsha meh Please changes these changes forme Carlos

6/14/02 Not final

- 1) Moore's 1834 Detector Showing a Top View of its Balance Beam Elements.
- Moore's 1834 Detector Showing a Side View of its Balance Beam Elements.
- George Howard 1849 Detector Showing its \$1 and \$2.50 Coin Holders on its One Swinging Arm which Partly Covers the Balance Beam and its Holders.
- 4) George Howard 1849 Detector Showing its One Swinging Arm Turned onto the Counterweight Side of the Fulcrum. The Overlapping \$10 and \$20 Coin Holders on the Balance Beam Cause Diagonal Slot Guages to be Used.
- George Howard 1849 Detector Showing a Side View of its Balance Beam and its One Partly Raised Swinging Arm.
- 6) Allender 1850 Detector with its Balance Beam Coin Holders on Each side of the Fulcrum. Its Separate Circular Weight is to be Placed in the \$1 Coin Holder for Testing the \$10 and \$20 Coins.
- Meyers 1850 Detector Showing its Two Swinging Arms with their Coin Holders Partly Covering the Balance Beam Coin Holders.

- 1) Moore's 1834 Detector for US \$2.50 and \$5 Showing a Top View of its Balance Beam Elements.
- Moore's 1834 Detector Showing a Side View of its Balance Beam Elements.
- 3) George Howard 1849 Detector Showing its \$1 and \$2.50 Coin Holders on its One Swinging Arm which Partly Covers the Balance Beam and its Other Coin Holders.
- 4) George Howard 1849 Detector Showing its One Swinging Arm Turned onto the Counterweight Side of the Fulcrum. The Overlapping \$10 and \$20 Coin Holders on the Balance Beam Cause Diagonal Slot Gueges to be Used.
- 5) George Howard 1849 Detector Showing a Side View of its Balance Beam and its One Partly Raised Swinging Arm.
- Allender 1850 Detector with its Balance
 Beam Coin Holders on Each side of the
 Fulcrum. Its Separate Circular Weight is
 to be Placed in the \$1 Coin Holder for
 Testing the \$10 and \$20 Coins.
- Meyers 1850 Detector Showing its Two Swinging Arms with their Coin Holders Partly Covering the Balance Beam Coin Holders.

- Moore's 1834 Detector Showing a Top View of its Baiance Beam Elements.
- Moore's 1834 Detector Showing a Side View of its Balance Beam Elements.
- George Howard 1849 Detector Showing its \$1 and \$2.50 Coin Holders on its One Swinging Arm which Partly Covers the Belance Beam and its Holders.
- 4) George Howard 1849 Detector Showing its One Swinging Arm Turned onto the Counterweight Side of the Fulcrum. The Overlapping \$10 and \$20 Coin Holders on the Balance Beam Cause Diagonal Slot Guages to be Used.
- George Howard 1849 Detector Showing a Side View of its Balance Beam and its One Partly Raised Swinging Arm.
- 6) Allender 1850 Detector with its Balance Beam Coin Holders on Each side of the Fulcrum. Its Separate Circular Weight is to be Placed in the \$1 Coin Holder for Testing the \$10 and \$20 Coins.
- Meyers 1850 Detector Showing its Two Swinging Arms with their Coin Holders Partly Covering the Balance Beam Coin Holders.

- Meyers 1850 Detector Showing \$1 and \$2.50 Coin Holders on its top Swinging Arm Turned onto the Counterweight Side of the Fulcrum, Exposing the Other Swinging Arm with the \$5 Coin Holder and Further Exposing the \$10 and \$20 Coin Holders on the Balance Beam.
- Meyers 1850 Detector Showing Both Swinging Arms turned onto the Counterweight Side of Fulcrum, Fully Exposing the \$10 and \$20 Coin Holders on the Balance Beam.
- Meyers 1850 Detector Showing a Side View of the Balance Beam with its Two Swinging Arms in Partly Raised Positions.

Top 9

8) Meyers 1850 Detector Showing \$1 and \$2.50 Coin Holders on one-of its/Swinging Arm/Turned onto the Counterweight Side of the Fulcrum, Exposing the Other Swinging Arm with the \$5 Coin Holder on the Balance Beam.

- 9) Meyers 1850 Detector Showing Both Swinging Arms turned onto the Counterweight Side of Fulcrum, Fully Exposing the \$10 and \$20 Coin Holders on the Balance Beam.
- Meyers 1850 Detector Showing a Side View of the Balance Beam with its Two Swinging Arms in Partly Raised Positions.

1.) Moore's 1834 Detector for US \$42.50 and \$5.



Moore Theyer.

2. Heorge Howard 1849 Detector Showing its Swinging Arm Partly Conering the Coin Halders on the Balance Beam.



Howard Slant view arm not himel

3. Storge Howard 1849 Detector Showing its swinging Arm Turned onto the Counterweight side of the Fulcrum.



Howard Arm turned 4

Allinder 1850 Detector with the Balance Beam Coin Holders on Both Sides of the Fulcrum. A Separate Circular Weight is Placed in the #1 Coin Holder for Testing ## \$10 and \$20 Coins on the Other Side of the Fulcrum.



Allander slanted view.



Meyers 1850 Relector Showing its Two Sunging Arms Partly Covering the Coin Holdies on the Balance Beam.



Meyers both arms over beam holders

Meyers 1850 Detector Strains ets Top Swinging Arm Aprile Bound on the Countimeight side of the Fulcrum and its other Swinging Arm over the Balance Beam.



Meyers brearm turned

9 Meyers 1850 Detector Showing Both Swinging Arms Furned Upside Down onto the Counterwight Side of the Fulcrum.



Meyers both arms turned



Meyers both arms turned



Meyers one arm turned



Howard arm not turned.



Meyers side new boit arms on bean with holders



Meyers top new with both arms ones beam with holders



Meyers name



Meyers name



HOWARDO3 COLOR





MOUREOL





amazon.com







OLYMPUS DIGITAL CAMERA


HOWARNO1 - 4-10



OLYMPUS DIGITAL CAMERA




HOWARDOL



ALLENDER








MEYERSOFWICH



OLYMPUS DIGITAL CAMERA



MEYERO3_4-10



OLYMPUS DIGITAL CAMERA

OLYMPUS DIGITAL CAMERA



MEYEROD -4-10



OLYMPUS DIGITAL CAMERA



WENERY OF LOOK

